

Potential Hazard found in home-heating units

A warning has been issued about a potential fire hazard in certain heat-recovery systems made and installed between 1991 and 2001.

Venmar Ventilation is asking owners to immediately turn off and unplug units and contact the company. Affected units are identified with the following model numbers on a silver or black label on the outside panel, with the letter X representing any number or letter:

Venmar brand: AEXX, EARC, 1XX, 40X and 40XXX models.

Venmar AVS brand: 1.X, 2.X, 30XX and 55XX models.

Flair brand: 30, 30XX, 55, 55XX, 85115 models.

vanEE brand: 10, 1XXX, 100XX, 20, 20XX and 90 models.

Sears brand under the OPTIMUM name and units sold under the Guardian name carrying the Broan brand 100X or 200X label.

Call Venmar at 866-441-4645 or visit <http://www.venmar.ca/MainTemplate.aspx?lang=en>

© Copyright 2006 Bell Globemedia Publishing Inc. All Rights Reserved.
Article Posted on 22/12/06