MARKHAM

BUILDER'S RECORD OF BUILDING INSPECTIONS FOR:

Municipal address________________________________ PROJECT PLAN NO. ________________

BUILDING PERMIT NO. __________________ SITE SUPERVISOR:_________________________

INSPECTION NOTES

FOOTING & FOUNDATION INSPECTIONS	FIELD INSPECTION REPORT NO. or as Marked on site	ITEM NO. on Report COMPLIED WITH √ (if applicable)		REMARKS
Footings to be cleaned	0000	1.	√	Footings cleaned, re-inspection requested.

BUILDER' S RECORD OF BUILDING INSPECTIONS FOR:

Municipal address________________________________ PROJECT PLAN NO. ________________

BUILDING PERMIT NO. ___________________ SITE SUPERVISOR:_________________________

INSPECTION NOTES

FRAMING INSPECTIONS (Including Heating and Plumbing Rough-in)	FIELD INSPECTION REPORT NO. or as Marked on site	ITEM NO. on Report COMPLIED WITH √ (if applicable)		REMARKS
First floor joist notched N/E corner	0000	1.	√	Repair detail by qualified designer

MARKHAM

BUILDER'S RECORD OF BUILDING INSPECTIONS FOR:

Municipal address________________________________ PROJECT PLAN NO. ________________

BUILDING PERMIT NO. __________________ SITE SUPERVISOR:_________________________

INSPECTION NOTES

INSULATION (including air and vapour barrier) INSPECTIONS	FIELD INSPECTION REPORT NO. or as Marked on site	ITEM NO. on Report COMPLIED WITH √ (if applicable)		REMARKS
Second Floor west wall, repair vapour barrier	0000	1.		Repair vapour barrier at floor level, west wall by bath tub.

BUILDER's RECORD OF BUILDING INSPECTIONS FOR:

Municipal address_____ PROJECT PLAN NO. _____

BUILDING PERMIT NO. _____ SITE SUPERVISOR:_____

INSPECTION NOTES

OCCUPANCY AND COMPLETION INSPECTIONS	FIELD INSPECTION REPORT NO. or as Marked on site	ITEM NO. on Report COMPLIED WITH √ (if applicable)		REMARKS
Door closer on door from garage to dwelling	0000	1.	√	Door closer not operating properly, to be replaced.